Evaluation of Advance Warning Signal Installation Phase I Summary Presentation

PREPARE TO STOP

Grant G. Schultz, Ph.D., P.E., PTOE

Assistant Professor, Brigham Young University

Ryan Peterson, EIT

Graduate Research Assistant, Brigham Young University

Bradley C. Giles

Systems Engineer, Wavetronix LLC

Dennis L. Eggett, Ph.D.

Associate Professor, Brigham Young University







OVERVIEW

- Background
- Design
- Signal timing
- Evaluation of data
- Effectiveness of installation
- Future research

BACKGROUND Site Location









BACKGROUND Safety Concerns at Signalized Intersections

- Dilemma zone (DMZ):
 - Not enough distance to stop
 - Not enough time to proceed
 - Improper signal timing
- Decision zone (DCZ):
 - Variation in driver behavior
 - Design assumptions not met
 - Motorists caught unaware
 - 90% 10% probability stopping distances





BACKGROUND Mitigation Techniques


- Advanced detection:
 - Reduce the number of vehicles caught in the DMZ at the onset of yellow
- Advance warning signals:
 - Warn motorists of impending signal changes in an effort to reduce the variation in motorist behavior





DESIGN

- Design of the project was completed by Project Engineering Consultants, Ltd.
- Three locations on Bangerter Highway:
 - Redwood Road
 - 2700 West
 - 13400 South
- One location on SR-201
- All intersections have posted speeds of 60 mph
- 85th percentile speeds were 63-64 mph



DESIGNThe Signs

- "Blank-Out" LED with sidemounted flashers
- Two rows of 14" letters
- 48" x 96" x 12" 300 lbs
- State-Furnished Item




DESIGNThe Installation

- Standard 75' mast arm and signal pole with mast arm cut to 55' length
- Horizontal damping "wing" at end of arm (2' x 8' panel)
- 65 mph design speed



- AWS placed 445' from stop bar; luminaire and video camera at 705'; detection zone at 755':
 - Based on a 2002 Nebraska Department of Roads study

DESIGN Typical AWS Layout



SIGNAL TIMING

- AWS comes on 6 seconds before end of green (lead-flash time)
- AWS remains on during the red
- AWS turns off once arterial turns green





EVALUATION

- Evaluation of the data and the effectiveness of the installations was conducted by BYU
- Evaluation metrics included:
 - Speed distributions
 - Red-light running (RLR)
 - Crash data
 - Decision-zone location


EVALUATIONData Collection Equipment – 13400 South

- BYU partnered with Wavetronix LLC to collect data using:
 - SmartSensor Advance[™] digital wave radar
 - Wireless communication devices
 - Contact closure devices
- In addition, UDOT provided the following equipment:
 - Voltage interface
 - Data logger
 - Laptop computer





EVALUATIONData Collection Equipment – 13400 South



EVALUATION Data Collection Equipment – 13400 South

- Speeds are recorded for each vehicle in 8 zones
- Red signal phases are time stamped
- Signal data is logged in the datalogger
- Speed data is logged on the laptop computer
- Post processing of the signal data and speed data allows red-light runners to be identified




EVALUATION Data Collection


- Data was collected for several months prior to activation of the system
- System activation occurred in June 2005 with data collected continuously since activation
- Data analysis included:
 - Before activation
 - Immediately after activation
 - 8 months after activation

- Speed data cumulative distributions:
 - Organized by time of day, approach, sensor zone, and number of seconds before red


Before, Northbound, 100 ft




Immediately After, Northbound, 100 ft



Speed data box plots:



Speed data statistical significance grids:



Red-light running data results:

	Before	% of Total	After	% of Total	% Change	Probability
NB	5.626	0.56	1.233	0.12	-78%	< .0001
SB	1.806	0.18	0.497	0.049	-72%	< .0001

^{*}Red-light running events per 1,000 entering vehicles (single approach stop bar counts only)


- RLR data was filtered with 4-second after red and 20 mph speed thresholds
- UDOT manual counts used to verify sensor data

EFFECTIVENESS Preliminary Conclusions


- AWS signs appear to affect driver behavior even when they are not flashing
- Motorists were traveling at higher and more constant speeds before the signs came on
- Motorists were slowing down and more motorists were stopping after the light turned yellow
- The total number of red-light runners at the intersections was reduced immediately after system activation

EFFECTIVENESS ight-month After Results


Before




Immediately After







EFFECTIVENESS ight-month After Results



EFFECTIVENESS Eight-month After Results

- Eight months after the system was installed:
 - Speed distributions returned to similar trends as before installation
 - Red light running increased to levels slightly higher than before installation in some instances
 - Crash rates decreased
 - Decision zone remained relatively constant
- Lead flash time theorized to be too conservative

FUTURE RESEARCH

- Modify lead-flash timing and evaluate effectiveness: $t_{E(DCZ)} = \frac{D_M + D_P}{-DCZ}$
 - Monthly evaluation
 - Monitor six to eight months after final changes made
- Follow-up research project:
 - Establish guidelines for future installations
 - Identify locations that fall within guidelines
 - Prioritize locations for future installations

QUESTIONS?

For more information, contact:

Grant G. Schultz, Ph.D., P.E., PTOE

Department of Civil & Environmental Engineering

Brigham Young University

gschultz@byu.edu

(801) 422-6332

